



Figure 2

The leakage inductance on the auxiliary-winding side causes high rectified voltages.